OXC-3430 Copy 25X1A

MEMORANDUM FOR: HQ. USAF

AFCIG-5

ATTENTION

: Colonel Leo P. Geary

SUBJECT

: H-42B Discrepancies

The H-43B Helicopter recently received by Hellis Air Force Base for assignment was in such marginal condition maintenance-wise, I feel you should be apprised of the major discrepancies found during the acceptance inspection.

- Urgent Action TOC's either Not Complied With or Improperly Complied With:
  - (1) 1B-43B-539, dated 30 Sept 1960, Starter Current Limitations. Not complied with as per TOC.
  - 1E-43B-580, Replacement of Cil (2) Pump Pressure Relief Valve Spring. (2J-T53-506.). Hot complied with and not entered on \$29-1. Engine 829. Block 8, shows non-compliance at Aerodex. Inc. "Lack of Parts".
  - 1H-43B-586, Modification of (3) Rescue Hoist Cable. Not complied with. Section 8 on aircraft 829 shows "Hook Inactive" at Hollowen AFB, New Mexico
  - (4) 15-43B-542, dated 17 May 1961, Replacement of Rotating Anti-Collision Light. TOC complied with but not is accordance with T.O., i.e., light installed from underside of shear-tie. Stiffner plate installed on octside of shear-tie.

NOTICE This material contains information affecting the national defense of the United States

within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws, Title 18, USC, Secs. 793 and 794, the transmission within the meaning of the espionage laws with the espionage laws with the espionage laws with the espionage laws with the e

25X1

DO Chi

1.1

OXC-3430 Page Two

- 18-43B-582, Additional Clearance for Elevator Control Tab Cable in Elevator Assembly. Not complied with as per existing directives.
- (6) 1H-43B-591, dated 10 April 1962, Inspection of Engine Mounts H-43B Relicopter. This T.O. was reflected on AFTO Form 829-1 on the aircraft as complied with. Upon inspection it was found that one mount was .090 beyond tolerance.
- ъ. Red Cross Discrepancies Found at Time of Arrival:
  - (1) Throttle out of rig. Engine can be cut-off from copilot's throttle grip.
  - (2) Throttle twist grip movement stiff but not binding.
  - (3) Tail boom attaching bolts loose.
  - (4) Elevator cable broken-approximately 80 percent of the strands!
- 2. Additional minor discrepancies and condition of aircraft paperwork would indicate little interest on the part of supervisory personnel to insure the transfer of a "safe" Request your assistance in insuring that aircraft and associated equipment assigned to the Project are scrutinized more closely prior to transfer.

FOR THE DEPUTY DIRECTOR (RESEARCH)

1	i	2	ľ	:	

STANLEY Y. BERRLI Colonel

25X1A

U - AUGUAL

Cy 2 - AC/DPD

" 3 - C/DB/DPD

This material contains infrance a we could the national defense of the United States within the meaning of the espanage laws, Title 18, USC ,Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

" 4 - SPB/DPDApproved 50/Relpase 2002/11/14 CIA-RDP81B00879R001000090014-1

" 6 - MS/DPD

" 7 - RI/DPD

## Approved For Release 2002 Approved For Relea

OXC-3431 Copy of of 5

1 May 1962

MEMORANDUM FOR: Chief, Security Branch, DPD

THROUGH

: Acting Chief, DPD

SUBJECT

: OXCART and IDEALIST Clearance for

25X1A

25X1

25X1

1. It is proposed that be cleared for OXCART and IDEALIST Projects. is the Deputy Chief of the Real Estate and Construction Division, Office of Logistics. He is a graduate engineer with considerable experience in Agency construction programs both overseas and in the ZI.

25X1A

2. It is planned to use as an engineering consultant to the Projects on a strictly problem area basis. By having available to the Materiel Staff to discuss technical engineering matters, project support in this specialized area will be ephydiced. Additionally, it is expected to use services as a back-up when necessary, to that presently available in our engineering function now performed by

25X1A 25X1A

25X1A

Chief, Materiel Staff. DPD

## Distribution:

O & 1 - ADDEE

cy 3 - AC/DPD

4 - MS/DPD

5 - RI/DPD

25X1

25X1A